

**Illinois Commerce Commission
Pipeline Safety
Exit Meeting Documentation Form**

Operator:	PEOPLES GAS LIGHT AND COKE CO.
Inspection Unit(s):	South Shop
Date of Meeting:	05/29/2015
Pipeline Safety Analyst:	Kevin Hecker
Exit Meeting Contact:	Charles Graham

Exit Statement

INSPECTION FINDINGS

Design Testing and Construction

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

Standard Inspection - Field Audit

Issues(s) Found:

Code Part [192.467(b)] - Staff accompanied John Racanelli on a follow up to a previously recorded low reading at 666 E. 83rd Place. An anode was placed on the service, but the reading taken today was still out of compliance at -.615. Further investigation revealed that the service line was not insulated from the inside service pipe, likely causing the low reading.

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]


Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]

Pipeline Safety Analyst Signature:



Operator Representative Signature:

